5/023/054



United States Department of the Interior

BUREAU OF LAND MANAGEMENT FILLMORE FIELD OFFICE

35 East 500 North Fillmore, UT 84631 http://enbb.blm.interwebdesign.com



In Reply Refer to: 3800 (U-010) UTU-075853

May 30, 2000

J KIRK FREEMAN 830 E 8080 S SANDY UT 84094

Dear Mr. Freeman:

On May 5, 2000, a field compliance inspection was conducted for your notice, 75853, the site of which was located in Section 23, T. 12 S., R. 10 W. This notice was accepted by our office on October 1, 1997, under the 43 CFR 3809 regulations for surface management. Based on our inspection, we have determined the surface disturbance related to your exploration has been satisfactorily reclaimed. Therefore, this notice case file is closed.

If you restart any mining related activity that causes surface disturbance, then you must re-notify this office at least 15 days prior to the start up of your operations.

Thank you for submitting your notice and for your support in proper management of public lands.

Sincerely,

Larry Garahana

Geologist

cc: D. Wayne Hedberg, UDOGM (S/023/054)

Lan C. England, 2157 S Lincoln St., Salt Lake City, UT 84106

Difference